


14-1991 Removing and installing resonance flap switchover valves

Preceding work:
 Removing and installing resonance intake manifold
 (14-1961).

Operation no. of operation texts and work units or standard texts
 and flat rates:
 14-1991

Engine 606.910



P07-6402-35

Vacuum lines (arrows) of resonance flap

switchover valves (Y22/6, Y22/7) detach, fit on.

Switchover valves (Y22/6, Y22/7) remove, install. To do this, unscrew bolts
 (99/10), screw in.

Notes

Pay attention to installation position and
 connection of vacuum lines (07.1-0005).