

J18	AH00.00-X-1000Z	Modification note	21.6.99
-----	-----------------	--------------------------	----------------

This microfiche replaces microfiche no. Z1 0008 06 01.

The previous microfiche is no longer valid and should be destroyed.

Newly included

Testing, repairing connecting rod	AR03.10-P-6111HA	G1
Removing and installing piston rings	AR03.10-P-7311HA	G2
Belt pulley/vibration damper as-built configuration	GF03.30-P-1600HA	N4
Belt pulley/vibration damper as-built configuration	GF03.30-P-1600HB	P4
Belt pulley/vibration damper as-built configuration	GF03.30-P-1600HC	B5
Belt pulley/vibration damper as-built configuration	GF03.30-P-1600HD	D5
Belt pulley/vibration damper as-built configuration	GF03.30-P-1600HE	F5

Revisions

Replacing front crankshaft radial seal	Modified parallel key (metal version) for hub at crankshaft Front crankshaft radial seal with reduced radial compression stress	AR03.20-P-3000HA	L2
--	--	------------------	----