B17	AS00.00-X-1000Z	Special tools	21 <i>.</i> 6.99
		•	

AS00.00-Z-0005-01A	Risk of accident as a result of vehicle	Secure vehicle to prevent it from moving	C17
	starting off when engine is running. Risk of	off.	
	injury as a result of bruises and burns if you	Wear closed and close-fitting work clothes.	
	insert your hands into engine when it is	Do not grasp hot or rotating parts.	
	being started or when it is running.		

C17	7 AS00.00-Z-0005-01A	Risk of accident as a result of vehicle	Secure vehicle to prevent it from	⚠ Danger!
		starting off when engine is running. Risk of	moving off.	
		injury as a result of bruises and burns if you	Wear closed and close-fitting work	
		insert your hands into engine when it is	clothes.	
		being started or when it is running.	Do not grasp hot or rotating parts.	

Possible dangers

Risk of accident

from vehicle starting off during starting operation (e.g. when testing compression pressure) as a result of gear engaged or when engine running and vehicles with automatic transmission as a result of selector lever position "P" or "N" not engaged (exception: some vehicles do not have a selector lever position "P").

Risk of injury

Severe injuries may be caused by freely rotating parts in the area of the running engine. The heat produced by the engine when it is operating can result in severe burns if contact is made with individual, unshielded parts.

Rules of conduct / Protective measures

- As a general rule, carry out work on the running engine only if this is absolutely essential.
- Before starting the engine, apply parking brake.
- On models with manual transmission, move gearshift lever into Neutral position.
- On models with automatic transmission, move selector lever into position "P" or "N" (exception: some vehicles do not have a selector lever position "P").
- On models which do not have selector lever position "P", secure selector lever to prevent it from being operated unintentionally.
- Wear closed and close-fitting work clothes.
- Take off any jewelry, such as chains, rings etc.
- If you have long hair, wear a suitable head cover.
- Before commencing work on the running engine, check to obtain a general picture of the positioning of parts which may be hot.
- When carrying out work when starting the engine or when engine is running, do not touch any hot and rotating parts.

First aid measures in the event of burns

- Do not rub the skin areas affected; flush with plenty of cold water and cover skin with sterile bandages.
- Immediately consult a physician.