

K18	ÄH00.00-X-1000Z	Modification note	1.7.99
------------	-----------------	--------------------------	---------------

This microfiche replaces microfiche no. Z1 0026 02 01 .

The previous microfiche is no longer valid and should be destroyed.

Newly included

Checking hydraulic valve clearance compensating elements	AR05.00-P-2010HW	B1
Removing, installing hydraulic valve clearance compensation elements (bucket tappets)	AR05.00-P-2011HY	D1
Timing chain drive as-built	GF05.10-P-4000HA	F1
Removing, installing tensioning rail	AR05.10-P-8127HA	A2
Removing and installing slide rail in cylinder head	AR05.10-P-8432HB	C2
Removing and installing slide rail in timing case cover	AR05.10-P-8484HA	G2
Checking camshaft timing	AR05.20-P-6015HB	M2

Revisions

--	--	--